| 1 | 2 . | 3 |
|------------------------------------|----------|--|
| 11. Modern. of Rajasamand | | |
| Irrgn. | 25.4.86 | —do— |
| Tamii Nadu | | |
| 1. Parambikulam Aliyar Ayacut | | |
| exten. (Consolidated) | 5.2.86 | do |
| 2. Modern. of Periyar Vagai St. II | 5.12.85 | do |
| 3. Modern. of Cauvery Delta | | |
| (Phase-I) | 8/85 | —do— |
| 4. Anaimaduvu Res. Scheme | 15.7.82 | —do— |
| ttar Pradesh | | |
| 1. Bewar Feeder Project | Nov. '84 | do |
| 2. Suheli | Feb. '79 | TAC note submitted to Planning Commission. |
| 3. Madhotande | Oct. '81 | —do— |
| 4. Khatima | Jan. '82 | —do— |

In addition to above 118 major and 67 medium schemes are under correspondence with the States for replies/compliance of CWC comments/TAC observations.

Modern technique of constructing roads of international standard

541. SHRI MOOL CHAND DAGA: Will the Minister of SURFACE TRANS-PORT be pleased to state:

- (a) whether it is a fact that modern technique of constructing roads of international standard is not available with us; and
- (b) if it is available, the reasons for which durable, strong and better roads and bridges are not built?

THE MINISTER OF STATE OF THE MINISTRY OF SURFACE TRANSPORT (SHRI RAJESH PILOT): (a) and (b). No, Sir, It is however not possible to switch over to modern techniques of road/bridge construction on account of our preference for

labour oriented policy, lack of infrastructure with the contracting agency and availability of adequate resources.

Collapse of Mandovi bridge in Goa

- 542. SHRI MOOL CHAND DAGA: Will the Minister of SURFACE TRANS-PORT be pleased to state:
- (a) the reasons for collapse of the Mandovi bridge in Goa;
- (b) whether responsibility, if any, has been fixed; and
 - (c) if so, the details thereof?

THE MINISTER OF STATE OF THE MINISTRY OF SURFACE TRANSPORT (SHRI RAJESH PILOT): (a) to (c). A Commission of Enquiry has been constituted by Government of Goa, Daman & Diu under