घोराडोंगरी रेलवे स्डेझन और सतपुरा विद्युत केन्द्र के बीच रेलवे लाइन

3704. भी यंगा **अरज वीकिल**ः न स रेल मझी यह बनाने की क्रुपा करंगे कि .

(क) क्या समीपस्थ रेलवे स्टेशन धोरा-डोगरी (मध्य प्रदेश) से सतपुडा विद्युत् केन्द्र स्थल तक रेल लिंक न होने के कारण उक्त विद्युत् केन्द्र के विस्तार कार्य मे रुकावट होन्नी; और

(ख) रेलवे साइडिंग का कार्यसमय पर पूरा करने के लिये रेलवे ढ़ारा क्या कार्य-वाही की जा रही है ?

रेस मन्त्रासय में उपसन्त्री (भी बूटा सिंह): (क) धोडाडोंबरी रेखन स्टमन मौर सतपुड़ा विजली घर के बीच एक साइडिंग की व्यवस्था करने के बारे मे सनुरोध प्राप्त हुया है मौर उस की जॉप की जा रही है ।

Flag Station between Chainage No. 6500 and 6809 at Bennifyur

3706. DR H. P SHARMA: SHRI R., V. BADE:

Will the Minister of RAILWAYS be pleased to state:

(a) whether there is a proposal to set up a flag station at Basantpur between Chainage No. 6500 and 6800 under the Kangra-Valley Rallway Realignment Project;

(b) if so, the steps taken in that regard; and

(c) the criteria taken into consideration for establishing Reg-stations along the realignment titl whether Beantpur fulfills these conditions? THE DEPUTY MINISTER IN THE MINISTRY OF RAILWAYS (SHRI BUTA SINGH): (a) No.

Written Answers

(b) Does not arise.

(c) Flag Stations are set up depending upon the needs of the traffic, proximity to adjoining stations and also taking into account the engineering aspects of the location Basantpur, however, does not fulfil the criteria

Consumption of diesel oil by Railways

3707. DR. K L. RAO. Will the Minister of RAILWAYS be pleased to state

(a) what is the amount of diesel oil consumed by the Railways in India and the portion thereof imported; and

(b) the differences in costs between diese! locomotives, coal locomotives and electric locomotives with respect to:----

- (i) the capital costs involved;
- (ii) the running costs involved; and
- (iii) the maintenance costs involved?

THE DEPUTY MINISTER IN THE MINISTRY OF RAILWAYS (SHRI BUTA SINGH): (1) About 6.88 lakk kilo litres of HSD oil was consumed during 1973-74. As the HSD oil stocks from indigenous production and imports are not stocked/supplied separately, it is not possible to indicate the quantity of imported HSD oil consumed by Railways.