

Title: Need to ensure proper maintenance of the WLL systems installed in Balasore Telecom Circle of Orissa.- Laid.

SHRI ARJUN CHARAN SETHI (BHADRAK) : The failure of the WLL systems installed in Balasore Telecom. District of Orissa has led to much discontentment amongst the subscribers of telephones. Many complaints have been made to the authority but no remedial measures seem to have been taken yet. This has further aggravated the situation because no cables are available in the telecom circle to provide alternative source of installation of telephones to the subscribers. Hence, I request the Government to take immediate steps to help ameliorate the situation for the best interest of the subscribers by providing cables as well as by maintaining WLL system properly.